



# 2EZ HS CARRIAGE RETROFIT

**SIMPLIFY MAINTENANCE.  
MAXIMIZE UPTIME.**





# EASIER ACCESS. SHORTER DOWNTIME. LOWER COSTS.

## THE CHALLENGE

Frustrated by the complexity and time spent servicing your Combi 2EZ High Speed Case Erector? Aligning the carriage bearings can be difficult and time intensive. Improper alignment leads to premature failure of the bearings.

Access to the old bearings is limited to the bottom, making replacement and alignment difficult. Most technicians remove the carriage assembly to access the bearings, making the process laborious and complicated.

Combi's all-new carriage retrofit simplifies maintenance and provides a more reliable, service friendly assembly.



### ❖ LIMITED ACCESS TO COMPONENTS

Critical service components are located within the frame, making routine maintenance more difficult and time consuming.

### ❖ HIDDEN COMPONENTS


Components are hidden from view by the carriage assembly, making it difficult to access and diagnose.

### ❖ CONFINED WORKSPACE

Harder access increases downtime and makes alignment of bearings difficult

### ❖ MORE DOWNTIME

Improper installation and misalignment increase equipment wear, resulting in more frequent repairs, higher parts cost, and downtime.



### ❖ EASY, OPEN SERVICE ACCESS

The carriage retrofit makes the bearings accessible from the top, and there is no need to disassemble the carriage assembly.

### ❖ IMPROVED COMPONENT VISIBILITY

The assembly has easy topside visibility making diagnostics easier.

### ❖ PERFECT ALIGNMENT EVERY TIME

Profile rails are bolted onto a machined plate, ensuring that the bearings are aligned every time.

### ❖ EXTENDED EQUIPMENT LIFE

Proper alignment and maintenance adds years to equipment life and reduces costly replacement and repair



**Call your Combi RSM or Mike Nicholas today to schedule your kit install.**

**MIKE NICHOLAS** Aftermarket Operations Manager

Phone: 234.360.8535 email: [mnicholas@combi.com](mailto:mnicholas@combi.com)